KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER:	BP-14-00558	**OWNER'S NAME:**	HANSEL MITZEL
DATE:	7/9/2015	**TYPE:**	Rough-in mechanical
TIME STARTED:	12:11 PM	**INSPECTOR:**	Justin Bennett
MAP NUMBER:	20-15-29051-0027		

	1. Mechanical Exhaust Ok
	2. Range vent not installed

INSTRUCTIONS: Verify range vent @ framing

NEXT INSPECTION: Framing

RE-INSPECTION FEE DUE? ☑ **NO** ☐ **YES** **$** _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

justin.bennett **@co.kittitas.wa.us**