## **INSPECTION REPORT**

PERMIT NUMBER:	BP-14-00703	OWNER'S NAME:	WEGNER
DATE:	1/20/2015	TYPE:	Framing
TIME STARTED:	11:59 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-19-13050-0005		
1. comple	ete electrical before fram	ing inspection	
2. nail panel edges at braced wall panel locations			
3. provide stamped truss sheets at framing inspection			
4. header to jack stud straps needed at portal frame areas per handout in packet			
INSTRUCTIONS: complete above, call for reinspection on exterior shear before covering			
NEXT INSPECTION:	re-inspect shear		
RE-INSPECTION FEE I	DUE? NO YES		\$
IF REQ	UIRED, RE-INSPECTION FEES MUST BE	PAID PRIOR TO SCHE	DULING A RE-INSPECTION
QUI	ESTIONS? PLEASE CONTACT THE INSPE	CTOR AT THE FOLLOW	/ING E-MAIL ADDRESS:
	jessi	ca.contratto @co.ki	ttitas.wa.us
	<b>TION REQUEST LINE:</b> <a href="www.co.kitti">www.co.kitti</a> 1 N. Ruby Street, Suite 2, Ellensburg, V		