INSPECTION REPORT

TYPE:

PERMIT NUMBER:

DATE:

BP-14-00705

1/20/2015

OWNER'S NAME: CONNELLY

Exterior shear

TIME STARTED:	9:23 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-18-08000-0048		
1. exterior shear ok			
INSTRUCTIONS: ok to cover			
NEXT INSPECTION: frame/plumb/mech			
RE-INSPECTION F	EE DUE? NO \(\big \)	/ES	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			