INSPECTION REPORT

BP-14-00708

PERMIT NUMBER:

OWNER'S NAME: CASCADE VIEW

DATE:	12/17/2014	TYPE:	Shearwalls
TIME STARTED:	12:29 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	18-18-27071-0139		
1. comp	olete bottom edge nailing	along front of	f house and garage
INSTRUCTIONS: (complete above, ok to cover		
NEXT INSPECTION	frame/plumb/mech		
RE-INSPECTION FE	E DUE? NO YE	S	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
C	UESTIONS? PLEASE CONTACT THE INSP	Sica.contratto @c	
	ECTION REQUEST LINE: www.co.kit 411 N. Ruby Street, Suite 2, Ellensburg,		