## **INSPECTION REPORT**

TYPE:

**PERMIT NUMBER:** 

DATE:

BP-14-00734

4/24/2015

OWNER'S NAME: LYTLE FAMILY TRUST

Shearwalls

TIME STARTED:		10:34 AM	IN	ISPECTOR:	Jessica Contratto	
MAP NUMBER:		19-14-03000-	0056			
1. interior shear ok						
INSTRUCTIONS: ok to cover						
NEVT INSPECTION: ()						
NEXT INSPECTION: fireplace rough in						
RE-INSPECTION FEE DUE? VES \$  IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION						
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:						
	jessica.contratto @co.kittitas.wa.us					
• INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 •						
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506						