KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER:	BP-14-00751	**OWNER'S NAME:**	NEW SUNCADIA LLC
DATE:	7/27/2015	**TYPE:**	Mechanical and plumbir
TIME STARTED:	1:28 PM	**INSPECTOR:**	Justin Bennett
MAP NUMBER:	20-15-29051-0018		

	1. Waste @ 7#/15 mins - Ok
	2. Draftstop installation Ok
	3. Verify fireplace vent piping product data to ensure rating for use
	4. Gas @ 5# - Must be 15#/15 mins
	5. Complete fire caulking at WH B Vent
	6. Complete fire seperation at furnace

INSTRUCTIONS: Complete corrections above

NEXT INSPECTION: Re-Inspection

RE-INSPECTION FEE DUE? ☑ **NO** ☐ **YES** **$** _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____justin.bennett **@co.kittitas.wa.us**