INSPECTION REPORT

PERMIT NUMBER:	BP-14-00837	OWNER'S NAME:	HAND
DATE:	1/22/2015	TYPE:	Re-inspection
TIME STARTED:	12:00 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	18-18-20010-0012		
1. Framir	ng/final ok		
INSTRUCTIONS:			
NEXT INSPECTION:	N/A		
RE-INSPECTION FEE I	DUE? NO YES		\$
IF REQU	UIRED, RE-INSPECTION FEES MUST BE	PAID PRIOR TO SCHE	DULING A RE-INSPECTION
QUI	ESTIONS? PLEASE CONTACT THE INSPI		
		ica.contratto @co.ki	
	TION REQUEST LINE: <u>www.co.kitt</u> 1 N. Ruby Street, Suite 2, Ellensburg, V		