KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER:	BP-15-00024	**OWNER'S NAME:**	JACKSON
DATE:	7/29/2015	**TYPE:**	Final
TIME STARTED:	10:48 AM	**INSPECTOR:**	Jessica Contratto
MAP NUMBER:	20-14-28601-0002		

	1. Range vent not installed
	2. Fireplace not functioning, gas not connected to tank
	3. permit card not on site. New one needed
	4. Access and sewer to be approved
	5. CO detector outside downstairs bedroom
	6. fresh air damper installed on air handler-ok
	7. Water heater to be switched for heat pump style to meet 1.5 energy credits. Not yet ins
	talled
	8. WUIC inspection from fire marshal required. Schedule with office. Inspections are Tues
	and Thurs
	9. blower door test complete

INSTRUCTIONS: complete above, re-inspect

NEXT INSPECTION: re-inspect

RE-INSPECTION FEE DUE? ☑ **NO** ☐ **YES** **$** _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

jessica.contratto **@co.kittitas.wa.us**