KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER:	BP-15-00193	**OWNER'S NAME:**	NELLI
DATE:	9/30/2015	**TYPE:**	Mechanical and plumbir
TIME STARTED:	1:31 PM	**INSPECTOR:**	Jessica Contratto
MAP NUMBER:	20-15-19050-0066		

	1. H2O is live-ok
	2. DWV not on test
	3. complete draftstops at upstairs duct penetrations to attic
	4. Range vent not installed yet. Sidewall termination to be seen at final
	5. Fireplace ok
	6. Gas at 18#-ok

INSTRUCTIONS: complete above, call for re-inspect on plumbing with framing inspection

NEXT INSPECTION: plumbing/framing

RE-INSPECTION FEE DUE? ☑ **NO** ☐ **YES** **$** _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____jessica.contratto **@co.kittitas.wa.us**