INSPECTION REPORT

PERMIT NUMBER: BP-15-00207 OWNER'S NAME: IVERSON

DATE:		7/29/2015	TYPE:	Exterior shear
TIME STARTED:		10:28 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:		20-14-19053-0002	2	
	1. tighten ເ	up nailing on header at g	arage portal frame	
	2. Note- w	indow above tubs needs	to be tempered	
INSTRUCTIONS: complete above, ok to cover				
NEXT INSPECTION: plumb/mech				
RE-IN:	SPECTION FEI		YES S MUST BE PAID PRIOR TO SCH	\$ HEDULING A RE-INSPECTION
	Q	UESTIONS? PLEASE CONTACT	THE INSPECTOR AT THE FOLLO	
			iessica.contratto @co	
			w.co.kittitas.wa.us/cds/red lensburg, WA 98926 • Main O	<u>ruest.asp</u> or 509-962-7694 ● ffice Line: 509-962-7506