INSPECTION REPORT

PERMIT NUMBER:		BP-15-00207	OWNER'S NAME:	IVERSON
DATE:		1/12/2016	TYPE:	Final
TIME STARTED:		10:53 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:		20-14-19053-0002		
	1. Blower do	oor test must be less than 5 ACH	I. Currently 5.14	
	2. No pass through attic access to garage from house. Attic access must be provided for			
	garage			
	3. Water heater ok			
	4. WUIC ok			
	5. Permit card not on site. Does a new one need to be brought out?			
	6. Truss correction cannot be seen from house side of attic			
INSTRUCTIONS: Complete above				
<u>'</u>				
NEVT INCOCCTION				
NEXT INSPECTION: re-inspection				
RE-INSPECTION FEE DUE? YES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
iessica.contratto @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •				