INSPECTION REPORT

PERMIT NUMBER: BP-15-00215 OWNER'S NAME: WEST

DATE:		9/17/2015	TYPE:	Exterior shear
TIME STARTED:		5:03 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:		20-14-24050-0517		
1	1. 4 MSTA48 straps missing			
2	2. all nailing ok			
INSTRUCTIONS: add straps, 2 can be seen inside. Take pics of other 2 below master bedroom				
NEXT INSPECTION: plumb/mech				
RE-INSPECTION FEE DUE? VES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
<u>iessica.contratto</u> @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •				
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506				