INSPECTION REPORT

PERMIT NUMBER: BP-15-00245 OWNER'S NAME: BUTLER

DATE:		8/14/2015	TYPE:	Framing
TIME STARTED:		1:06 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:		20-15-36058-0003		
	1. framing o	ming ok		
	2. anchors and shot pin spacing ok			
INSTRUCTIONS:				
NEXT INSPECTION: Final/fire marshal final				
RE-INSPECTION FEE DUE? VES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
<u>iessica.contratto</u> @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 •				
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506				