INSPECTION REPORT

PERMIT NUMBER:		BP-15-00364	OWNER'S NAME:	REIMER	
DATE:		9/30/2015	TYPE:	Mechanical and plumbir	
TIME STARTED:		1:55 PM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		20-15-19051-0055			
	1. Gas at 30#-ok				
	2. H2O is live at 55#-ok				
	3. DWV on stack-ok				
	4. Exhaust duct ok				
	5. Plumbing ok				
	6. Fireplace not installed yet				
INSTRUCTIONS:					
NEXT INSPECTION: framing					
RE-INSPECTION FEE DUE? V NO YES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	iessica.contratto @co.kittitas.wa.us				
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 					