INSPECTION REPORT

OWNER'S NAME: NANSEL

PERMIT NUMBER: BP-15-00384

DATE:	8/18/2015	TYPE:	Radiant heat
TIME STARTED:	11:38 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-13-11050-0030		
1. Hydro	@ 100#/15 mins - Ok		
2. Installation Ok			
3. Mechanical Final Ok			
INSTRUCTIONS: Mechanical Final Ok			
NEXT INSPECTION	N: N/A		
RE-INSPECTION F	EE DUE? V NO	YES	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iustin_bennett @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 			
TIT N. Nuby Street, Suite 2, Literisburg, WA 30320 Viviani Office Line. 303-302-7300			