KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER:	BP-15-00754	**OWNER'S NAME:**	BERG
DATE:	1/4/2016	**TYPE:**	Plumbing
TIME STARTED:	9:45 AM	**INSPECTOR:**	Jeremy Haberman
MAP NUMBER:	18-18-27020-0013		

	1. Plumbing Rough In OK. DWV at 5#/15min. Supply at 50#/15min. OK
	2. Gas Line OK. 20#/15min. OK.
	3. Unable to Verify Fireplace Clearances. Manual Not Onsite. Will Verify at Framing.
	4. NOTE: Verify L&I Cover Inspection at Framing.

INSTRUCTIONS: Leave Fireplace Manual Onsite to Verify Clearances. OK to Call for Framing.

NEXT INSPECTION: Framing.

RE-INSPECTION FEE DUE? ☑ **NO** ☐ **YES** **$ _____**

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____jeremy.haberman **@co.kittitas.wa.us**