KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER:	BP-15-00950	**OWNER'S NAME:**	CIRAULO
DATE:	12/10/2015	**TYPE:**	Anchoring
TIME STARTED:	2:14 PM	**INSPECTOR:**	Jessica Contratto
MAP NUMBER:	18-19-30062-0001		

	1. Racking not installed yet

INSTRUCTIONS: Reschedule when ready

NEXT INSPECTION: Re-inspect

RE-INSPECTION FEE DUE? ☑ **NO** ☐ **YES** **$** _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____jessica.contratto **@co.kittitas.wa.us**