



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-16-00584

OWNER'S NAME: KIDWELL

DATE: 12/22/2016

TYPE: Exterior shear

TIME STARTED: 2:00 PM

INSPECTOR: Jessica Contratto

MAP NUMBER: 20-15-29051-0028

1. CS14 straps missing at bunk room, garage corner(2) and (1)each side of attic access door
2. Exterior nailing and LTP clips ok

INSTRUCTIONS: Ok to cover exterior, straps can be seen interior

NEXT INSPECTION: Plumb/mech

RE-INSPECTION FEE DUE?



NO



YES

\$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL

ADDRESS: _____ [jessica.contratto @co.kittitas.wa.us](mailto:jessica.contratto@co.kittitas.wa.us)

INSPECTION REQUEST LINE: 509-962-7694

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506