



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-16-00625

OWNER'S NAME: BARANOWSKI

DATE: 4/10/2017

TYPE: Mechanical and plumbir

TIME STARTED: 12:32 PM

INSPECTOR: Jessica Contratto

MAP NUMBER: 20-15-20058-0088

1. Heating and exhaust duct ok
2. Gas at 20#-ok
3. Nail plates installed on plumbing penetrations-ok
4. Fireplace rough in ok
5. Interior shear not complete yet

INSTRUCTIONS: Complete electrical install

NEXT INSPECTION: Framing

RE-INSPECTION FEE DUE? NO YES \$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL
ADDRESS: _____ [jessica.contratto @co.kittitas.wa.us](mailto:jessica.contratto@co.kittitas.wa.us)

INSPECTION REQUEST LINE: 509-962-7694

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506