INSPECTION REPORT

INSPECTION REPORT			
PERMIT NUMBER:	BP-16-00687	OWNER'S NAME:	CARLSON
DATE:	3/13/2017	TYPE:	Exterior shear
TIME STARTED:	12:48 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-20058-0132		
			ration wall
INSTRUCTIONS: Ok to cover exterior			
NEXT INSPECTION: Plumb/mech			
RE-INSPECTION FEE			\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			

INSPECTION REQUEST LINE: 509-962-7694

ADDRESS:__

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

iessica.contratto @co.kittitas.wa.us