



KITITITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-17-00290

OWNER'S NAME: FIFE

DATE: 6/5/2017

TYPE: Gas piping

TIME STARTED: 10:16 AM

INSPECTOR: Jessica Contratto

MAP NUMBER: 17-19-06053-0014

1. Gas at 28#-ok

INSTRUCTIONS: Ok to hook up meter. New furnace and AC installation still needs inspection to close out permit

NEXT INSPECTION: Mechanical

RE-INSPECTION FEE DUE? NO YES \$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL
ADDRESS: _____ [jessica.contratto @co.kittitas.wa.us](mailto:jessica.contratto@co.kittitas.wa.us)

INSPECTION REQUEST LINE: 509-962-7694

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506