## **INSPECTION REPORT**

PERMIT NUMBER:	BP-17-00454	OWNER'S NAME:	HEIN
DATE:	7/11/2017	TYPE:	Final
TIME STARTED:	2:56 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	18-18-27070-0074		
1. Gas at 22#-ok 2. Furnace and A 3. Air conditione	AC install ok		
INSTRUCTIONS: Have gas meter set, address AC issue  NEXT INSPECTION: Final  RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION  QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
		essica.contratto @	
	תטטוובטט <u> </u>	<u> </u>	co.niculas.wa.us

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506