INSPECTION REPORT

BP14-00244

PERMIT NUMBER:

OWNER'S NAME: JACOBSON

DATE:		9/25/2014	TYPE:	Frame-Plumb-Mech	
TIME STARTED:		2:56 PM	INSPECTOR:	Amber Green	
MAP NUMBER:		20-14-02061-00	01		
	1. DWV ((H2O/15min) - OK			
	2. H2O (working pressure) - OK				
	3. Gasline (15#/15min) - OK				
	4. Complete exhaust fan in bathroom.				
	5. Provide updated floor plan for dormir and bonus room area.				
INSTRUCTIONS: Ok to Insulate					
NEXT INSPECTION: Insulation					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	amber.green @co.kittitas.wa.us				
 ■ INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 					

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506