INSPECTION REPORT

PERMIT NUMBER: FO-14-00017

OWNER'S NAME: CLARK

DATE:	11/7/2014	TYPE:	Radiant heat
TIME STARTED:	11:33 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-29050-0219		
1. hydronics at 100#-ok			
2. slab insulation ok			
INSTRUCTIONS: ok to pour			
NEXT INSPECTION: frame/plumb/mech			
RE-INSPECTION	FEE DUE? NO \(\bigcup\)	/ES	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			