## **INSPECTION REPORT**

PERMIT NUMBER:	FO-14-00048	OWNER'S NAME:	SINNETT
DATE:	8/7/2014	TYPE:	Foundation walls
TIME STARTED:		INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-14-14050-0925		
1. post ac	ddress		
2. finish l	ast 8 hold down straps		
INSTRUCTIONS: ok to pour after straps are installed			
NEXT INSPECTION:	slab insulation		
RE-INSPECTION FEE	DUE? NO YES	5	\$
IF REQ	UIRED, RE-INSPECTION FEES MUST BI	E PAID PRIOR TO SCHE	DULING A RE-INSPECTION
QUI	ESTIONS? PLEASE CONTACT THE INSP		
		ica.contratto @co.k	
	<b>TION REQUEST LINE: <u>www.co.kitt</u></b> 1 N. Ruby Street, Suite 2, Ellensburg, \		