INSPECTION REPORT

PERMIT NUMBER:

FO-14-00113 OWNER'S NAME: CONNELLY/KANWETZ

DATE:	11/14/2014	TYPE:	Foundation walls
TIME STARTED:	4:37 PM 17-18-08000-0048	INSPECTOR:	Jessica Contratto
INSTRUCTIONS: (ok to pour walls		
NEXT INSPECTION:	floor framing		
RE-INSPECTION FE	E DUE? NO YE	S	\$
IF RE	QUIRED, RE-INSPECTION FEES MUST B	E PAID PRIOR TO SC	CHEDULING A RE-INSPECTION
Q	UESTIONS? PLEASE CONTACT THE INSF	PECTOR AT THE FOLL sica.contratto @co	
▲ INICDE	ECTION REQUEST LINE: www.co.kit		
	.11 N. Ruby Street, Suite 2, Ellensburg,		