INSPECTION REPORT

PERMIT NUMBER:	FO-14-00114	OWNER'S NAME:	GROENKE
DATE:	10/27/2014	TYPE:	Foundation walls
TIME STARTED:	11:44 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	18-19-32063-0002		
1. ok to p	our walls		
INSTRUCTIONS: OK	to pour		
NEXT INSPECTION:	shearwalls		
RE-INSPECTION FEE I	DUE? NO YES		\$
	UIRED, RE-INSPECTION FEES MUST BE		
QUI	ESTIONS? PLEASE CONTACT THE INSPI jess	ECTOR AT THE FOLLOW ica.contratto @co.k	
	TION REQUEST LINE: www.co.kitt 1 N. Ruby Street, Suite 2, Ellensburg, V		