



507 N. Nanum Street, Suite 102  
 Ellensburg, WA 98926  
 T: 509.962.7515 F: 509.962.7581  
[www.co.kittitas.wa.us/health/](http://www.co.kittitas.wa.us/health/)

## Soil Log Evaluation for Land Use

Soil Log Evaluation fee is non-refundable after service has been provided.

Owner Name: Thorp Landing LLC

Tax Parcel #: 493233 & 443233

Site Address: Goodwin Rd

Acreage Size: 54.39

City, State, Zip: Thorp, Wa 98946

Owner/Agent Signature: \_\_\_\_\_

Plat Name (map must be included): Thorp Landing LP-23-00001

E-mail: joel@centralpavingllc.com

| Soil Log # 1 |         | Lot # 1                 |                      |
|--------------|---------|-------------------------|----------------------|
| Depth        | Texture | Structure               | Color                |
| Feet         |         |                         |                      |
| 1-           | Si.L    | Moderate Angular Blocky | Pale Brown           |
| 2-           |         |                         |                      |
| 3-           |         |                         |                      |
| 4-           |         |                         |                      |
| 60"5-        | Si.C.L  | Strong angular shoky    | Mottled Yellow Brown |
| 6-           |         |                         |                      |

| Soil Log # 2 |                    | Lot # 2                    |                         |
|--------------|--------------------|----------------------------|-------------------------|
| Depth        | Texture            | Structure                  | Color                   |
| Feet         |                    |                            |                         |
| 1-           | Si. C. L           | Strong Columnar            | Black                   |
| 24"2-        |                    |                            |                         |
| 3-           | Si. C. L           | Strong Columnar w/ Cobbles | Mottled Very Dark Brown |
| 48"4-        |                    |                            |                         |
| 5-           | Bottom of Test Pit |                            |                         |
| 6-           |                    |                            |                         |

| Soil Log # 3 |                  | Lot # 3                       |       |
|--------------|------------------|-------------------------------|-------|
| Depth        | Texture          | Structure                     | Color |
| Feet         | Si.C.L           | Moderate<br>Angular<br>Blocky | Black |
| 1-           |                  |                               |       |
| -            |                  |                               |       |
| 2-           | C.L              | Platy                         | Black |
| 30"<br>3-    |                  |                               |       |
| -            |                  |                               |       |
| 4-           | H <sub>2</sub> O |                               |       |
| 60"<br>5-    |                  |                               |       |
| -            |                  |                               |       |
| 6-           |                  |                               |       |

| Soil Log #4 |                    | Lot # 4   |       |
|-------------|--------------------|-----------|-------|
| Depth       | Texture            | Structure | Color |
| Feet        | Si. Col            | Weak      | Black |
| 1-          |                    |           |       |
| -           |                    |           |       |
| 2-          |                    |           |       |
| -           |                    |           |       |
| 3-          |                    |           |       |
| -           |                    |           |       |
| 4-          |                    |           |       |
| -           |                    |           |       |
| 60"5-       | Bottom of Test Pit |           |       |
| -           |                    |           |       |
| 6-          |                    |           |       |

EH Inspector's Signature: \_\_\_\_\_

Date: \_\_\_\_\_

10-14-2024

EH Version: 3 Supersedes: 2 Date Adopted: 4/10/24 Modified By: LG Approval By: Jesse Cox



507 N. Nanum Street, Suite 102  
 Ellensburg, WA 98926  
 T: 509.962.7515 F: 509.962.7581  
 www.co.kittitas.wa.us/health/

## Soil Log Evaluation for Land Use

Soil Log Evaluation fee is non-refundable after service has been provided.

Owner Name: Thorp Landing LLC  
 Site Address: Goodwin Rd  
 City, State, Zip: Thorp, Wa 98946  
 Plat Name (map must be included): Thorp Landing LP-23-00001

Tax Parcel #: 493233 & 443233

Acreage Size: 54.39

Owner/Agent Signature: \_\_\_\_\_

E-mail: joel@centralpavingllc.com

| Soil Log # 5 Lot # 5 |          |                         |       |
|----------------------|----------|-------------------------|-------|
| Depth                | Texture  | Structure               | Color |
| Feet                 |          |                         |       |
| 1-                   | Si. C. L | Moderate Angular Blocky | Black |
| -                    |          |                         |       |
| 2-                   |          |                         |       |
| -                    |          |                         |       |
| 3-                   | 45"      | Massive                 |       |
| -                    |          |                         |       |
| 4-                   |          |                         |       |
| -                    |          |                         |       |
| 5-                   |          |                         |       |
| -                    |          |                         |       |
| 6-                   |          |                         |       |

| Soil Log # 6 |          | Lot # 6            |       |
|--------------|----------|--------------------|-------|
| Depth        | Texture  | Structure          | Color |
| Feet         | Si. C. L | Strong<br>Columnar | Black |
| 1-           |          | Weak<br>Blocky     |       |
| -            |          |                    |       |
| 2-           |          |                    |       |
| -            |          |                    |       |
| 3-           | 57"      | Massive            |       |
| -            |          |                    |       |
| 4-           |          |                    |       |
| -            |          |                    |       |
| 5-           |          |                    |       |
| -            |          |                    |       |
| 6-           |          |                    |       |

| Soil Log # 7 Lot # 7 |          |                       |               |
|----------------------|----------|-----------------------|---------------|
| Depth                | Texture  | Structure             | Color         |
| Feet                 |          |                       |               |
| 1-                   | Si. C. L | Strong Angular Blocky | Black         |
| -                    |          |                       |               |
| 2-                   |          |                       |               |
| -                    |          |                       |               |
| 3-                   | 58"      | Massive               | Mottled Black |
| -                    |          |                       |               |
| 4-                   |          |                       |               |
| -                    |          |                       |               |
| 5-                   |          |                       |               |
| -                    |          |                       |               |
| 6-                   |          |                       |               |

| Soil Log # 8 Lot # 8 |          |                            |               |
|----------------------|----------|----------------------------|---------------|
| Depth                | Texture  | Structure                  | Color         |
| Feet                 |          |                            |               |
| 1-                   | Si. C. L | Moderate Subangular Blocky | Black         |
| -                    |          |                            |               |
| 2-                   |          |                            |               |
| -                    |          |                            |               |
| 3-                   | 64"      | Bottom of test pit         | Mottled Black |
| -                    |          |                            |               |
| 4-                   |          |                            |               |
| -                    |          |                            |               |
| 5-                   |          |                            |               |
| -                    |          |                            |               |
| 6-                   |          |                            |               |

EH Inspector's Signature: \_\_\_\_\_

Date: 10-14-2024

EH Version: 3 Supersedes: 2 Date Adopted: 4/10/24 Modified By: LG Approval By: Jesse Cox



507 N. Nanum Street, Suite 102  
 Ellensburg, WA 98926  
 T: 509.962.7515 F: 509.962.7581  
 www.co.kittitas.wa.us/health/

## Soil Log Evaluation for Land Use

Soil Log Evaluation fee is non-refundable after service has been provided.

Owner Name: Thorp Landing LLC

Site Address: Goodwin Rd

City, State, Zip: Thorp, Wa 98946

Plat Name (map must be included): Thorp Landing LP-23-00001

Tax Parcel #: 493233 & 443233

Acreage Size: 54.39

Owner/Agent Signature: \_\_\_\_\_

E-mail: joel@centralpavingllc.com

| Soil Log # 9 |          | Lot# 9                        |                 |
|--------------|----------|-------------------------------|-----------------|
| Depth        | Texture  | Structure                     | Color           |
| Feet         | Si. C. L | Moderate<br>Angular<br>Blocky | Black           |
| 1 -          |          |                               |                 |
| -            |          |                               |                 |
| 2 -          |          |                               |                 |
| -            |          |                               |                 |
| 3 -          |          |                               |                 |
| -            |          |                               |                 |
| 48" 4 -      |          | Massive                       | Yellow<br>Brown |
| -            |          |                               |                 |
| 5 -          |          |                               |                 |
| -            |          |                               |                 |
| 6 -          |          |                               |                 |

| Soil Log # 10 |         | Lot # 10                      |                 |
|---------------|---------|-------------------------------|-----------------|
| Depth         | Texture | Structure                     | Color           |
| Feet          | Si. C.L | Moderate<br>Angular<br>Blocky | Black           |
| 1-            |         |                               |                 |
| -             |         |                               |                 |
| 2-            |         |                               |                 |
| -             |         |                               |                 |
| 36 3-         | C.L     | Weak<br>Blocky                | Yellow<br>Brown |
| -             |         |                               |                 |
| 4-            |         |                               |                 |
| -             |         |                               |                 |
| 5-            |         |                               |                 |
| 65 6-         | Massive |                               |                 |
| -             |         |                               |                 |

| Soil Log # |         | Lot #     |       |
|------------|---------|-----------|-------|
| Depth      | Texture | Structure | Color |
| Feet       |         |           |       |
| 1-         |         |           |       |
| -          |         |           |       |
| 2-         |         |           |       |
| -          |         |           |       |
| 3-         |         |           |       |
| -          |         |           |       |
| 4-         |         |           |       |
| -          |         |           |       |
| 5-         |         |           |       |
| -          |         |           |       |
| 6-         |         |           |       |

| Soil Log # |         | Lot #     |       |
|------------|---------|-----------|-------|
| Depth      | Texture | Structure | Color |
| Feet       |         |           |       |
| 1-         |         |           |       |
| -          |         |           |       |
| 2-         |         |           |       |
| -          |         |           |       |
| 3-         |         |           |       |
| -          |         |           |       |
| 4-         |         |           |       |
| -          |         |           |       |
| 5-         |         |           |       |
| -          |         |           |       |
| 6-         |         |           |       |

EH Inspector's Signature: \_\_\_\_\_

Date: \_\_\_\_\_

10-14-2024

EH Version: 3 Supersedes: 2 Date Adopted: 4/10/24 Modified By: LG Approval By: Jesse Cox

THORP LANDING  
 PART OF SECTION 11, T. 18 N., R. 17 E., W.M.  
 KITTITAS COUNTY, WASHINGTON  
 - PRELIMINARY PLAT -




Blue - Domestic Water  
 Green - Irrigation  
 Red - Power/Communication

Transformer



- LEGEND
- FENCE
  - WELL
  - ⊙ POINT OF DIVERSION

- POINTS OF DIVERSION
- A CERT. S-4-3546-J  
AFN 20180800080  
1500' N & 200' E  
OF S 1/4 COR
  - B CERT. S-4-3546-J  
AFN 20180800080  
1500' N & 200' E  
OF S 1/4 COR
  - C CERT. S-4-3546-J  
AFN 20180800080  
1500' N & 200' E  
OF S 1/4 COR
  - D CERT. S-4-3546-J  
AFN 20180800080  
1500' N & 200' E  
OF S 1/4 COR
  - E CERT. S-4-3546-J  
AFN 20180800080  
1500' N & 200' E  
OF S 1/4 COR



ZONE: AG 5  
 ASSessor's NO. 492233 & 442333  
 SOURCE OF WATER: GROUP B WATER SYSTEM  
 SEWER SYSTEM: SEPTIC TANKS  
 DRAINAGE: AS PER KITTITAS CO. STANDARDS  
 ACCESS: PRIVATE ACCESS ROAD & COUNTY ROAD N/4  
 FLOOD ZONES SHOWN HEREON BASED ON FEMA FIRM PANELS 50037C 10300 & 10410.  
 VEGET. DATA = UNKNOWN BASED ON THIS TO NOS. MONUMENT AL2591.  
 CONTAINS BASED ON RED LINES COMPLETED 11/17/22 AND ARE ASSUMED TO 1' CONTINUED INTERVAL.



CRUSE & ASSOCIATES  
 PROFESSIONAL LAND SURVEYORS  
 217 E. 2nd St., Suite 200  
 Ellensburg, WA 98926  
 (509) 882-4242

X = Soil Log