




SOIL LOG FOR SHORT PLAT
INSPECTION RESULTS

507 N Nanum St., Suite 102, Ellensburg, WA 98926
509-962-7515
<https://www.co.kittitas.wa.us/health/>

Account Name: Blanken, Alexa Account # SE-26-00013
XXX MASTERSON RD, CLE ELUM 98922 98922, WA Parcel # 961873



Inspector	Inspection Type	Inspection Date	Status	Comments
Share Johnson	SOIL LOG INSPECTION	7/31/2026	APPROVED	
Group	Task Description	Status	Comments	
OBSERVATION	Soil Log 1: Depth/Texture/Structure/Color	PASSED	48" Type 5/ Strong/ Light Brown	
	Soil Log 2: Depth/Texture/Structure/Color	PASSED	48" SAME AS LOG 1	
	Field Observations	YES	Soil Logs done for parcel A1. Soil log was done at bottom of slope.	



MLH SP-24-00014