

FIRE LIFE SAFETY INSPECTION REPORT

Occupancy/ FD #: 002-026-0007 Map #: 18-18-25030-0015 Inspection Date: 01/27/2014		
Business Name: The Grove	Business phone number: 962-4010	
Address: 2420 Airport Road Ellensburg, WA 98926 Mailing Address: 2420 Airport Road Ellensburg, WA 9892		
Type of Business: Apartment complex	Business contact person: Jon Backus- 704-975-4520	
Occ Group: <u>R-2</u> Sq. Ft: <u>varies</u> Const. Type: <u>V-A</u> Sprinklers: <u>X</u> Alarms: <u>X</u> Fixed:		
Permits: Special Notes: Building 7		

A fire inspection has been conducted on your property. During this inspection conditions affecting fire safety were noted. In accordance with the International Building Code and International Fire Code, it is necessary that the items listed below be given your prompt attention.

A. Exterior Assessment	E. Fire Alarm System	I. Kitchen Suppression
1 - Building number not posted	1 - Annual Service needed	1 - Cleaning of hood and duct
2 - Obstructed FDC	2 - Devices obstructed	2 - Illegal cooking operation
3 - Obstructed fire hydrant	3 - Alarm Maintenance	3 - Six month service needed
4 - Gas meter protection	F. Flammable/Combustible	J. Automatic Sprinkler
5 - Storage proximity	1 - Storage cabinet	1 - Annual service needed
6 - Storage under eaves	2 - Improper housekeeping	2 - FDC cap needed
B. Exits	3 - No storage area	3 - Hanging material
1 - Exit travel	4 - Close to heating appliance	4 - Sprinkler clearance
2 - Exits obstructed	5 - Fueled equipment	5 - Provide sprinkler protection
3 - Panic hardware	6 - Oily rags	6 - Damaged/Painted heads
4 - Number of exits	7 - Compressed gas tanks	7 - Spare heads and/or wrench
5 - Unapproved locking devices	8 - Equipment rooms	K. Fuel Dispensing
6- Openable without tight grasping or twisting	9- Secondary Containment	1 - Fire extinguisher
7-Remove Bolt Locks or Dead Bolts		2 - Emergency shutoff
C. Exit Lighting and Signs	G. Electrical	3 - Provide signage
1 - Exit signs battery backup	1 - Extension cord usage	4 - Replace hoses
2 - Exit signs required	2 - Electrical panel labeling	L. Compressed Gas
3 - Emergency lighting	3 - Portable heaters	1-Cylinders shall be secured
4 - Exit sign burnt out	4 - Improper power strip usage	2- Protective caps shall be in place when not in use.
5 - "This door to remain unlocked" sign	5 - Power Panel obstructed	M. Storage
D. Extinguishers	6 - No cover plate	1-Ceiling Clearance
1 - Class K extinguisher	7 - Multi-plug adapter	2- Equipment rooms
2 - Number of extinguishers		3- Storage under stairs or in attic
3 - Extinguisher placement	H. Fire Walls and Doors	N. Other corrections required
4 - Extinguisher obstructed	1 - Restrained fire door	1-See detailed report
5 - Extinguisher maintenance	2 - Breached wall or ceiling	
6 - Signs indicating location	3 - Fire assembly needs repair	X. No apparent Violations Noted
7- Minimum size 2A-10BC		1 - No apparent Violations

Remarks:

Building 7- Please provide a copy of the annual sprinkler and fire alarm system confidence test reports when completed. Replacing pull station glass pins, when confidence test is done. This Fire Inspection report also serves as your invoice. Please remit payment in the amount of 0.00 within 30 days.

Inspector's Name: Bill Steele

Inspector's Phone #: 509-962-7657

E-mail address: _____fixitellensburg@gogrove.com

Received by Jon

Compliance with the preceding requirements shall be effective immediately.

A re-inspection shall be conducted on/or after _____ days to verify full compliance.

You are hereby notified to remedy the conditions as stated above immediately. After the conditions have been abated mail a copy of the notice within days

After the conditions have been abated, mail a copy of the notice within ______ days including a signature certifying completion.

I CERTIFY THAT THE VIOLATIONS SPECIFIED ABOVE HAVE BEEN CORRECTED.

PRINT NAME